

## Departure Procedure runway 07

After the run-up continue to hold short of the runway until the winch caution light is out.

When the winch caution light is out continue with an initial backtrack until the winch position.

Wait for a “Thumps up” or a radio call “XX-XXX, weelde radio, your number one for backtrack at your own discretion”

After receiving backtrack information continue with backtrack until the threshold.

